

Download Tbi Jeep Idle Speed Motor

my 90 yj 2.5L TBI wont drop rpms after warming up. it seems that the idle speed motor is not moving, it doesnt move when shutting the motor off either.1988 Jeep Comanche MJ Renix 2.5L I4 2WD AX-4 4 Speed Idle Speed Motor or Idle Speed Actuator adjustment procedure: - With engine up to operating ...Symptoms of a Bad or Failing Idle Control Valve ... The valve or motor is controlled by the engine ... This may result in an unusually high or low idle speed, ...Automatic Idle Speed (AIS) Motors and Sensors, and Idling on Chrysler, ... The automatic idle speed motor ... (TBI) 2.2 and 2.5 liter ...